

Volume Level Tops Out at 11 When Using Apple CarPlay™

AFFECTED VEHICLES

2017 NSX

When using Apple CarPlay, does the volume level top out at **11** when you try to adjust it using the audio remote controls on the steering wheel or the volume control on the Display Audio? We're aware of this issue and have it under investigation.

In the meantime, you can restore the full volume level range by simply restarting the phone. Just press and hold the Sleep/Wake button until the red slider appears, then drag the slider to turn the phone completely off. Wait a few seconds, then press and hold the Sleep/Wake button again until you see the Apple logo.