

## Chatter or Rattle Near Left or Right Door Tweeter

### AFFECTED VEHICLES

2017 NSX

When driving on a rough road, are you hearing a chatter or rattle that seems to be coming from near the left or right door tweeter, close to the base of the A-pillar? Chances are the door outer seal (window run channel) is causing it.

To quiet things down, apply a thin, even layer of Shin-Etsu Silicone Grease (P/N 08798-9013) to the inner edges of the seal with Q-tips, then raise and lower the window glass several times. Be sure to wipe off any excess grease you see with the window raised.



Taking these steps should do the trick, but if it doesn't, then, of course, continue with normal system troubleshooting.